

Basic Lathe Operation

- 1 Safety Glasses
- 1 60 Degree Center Gauge
- 1 Inch Screw Pitch Gauge
- 1 10" or 12" Adjustable Wrench
- 2 ½" x ½" High Speed Steel Tool Bit Blank
- 1 #4 Center Drill (High Speed Steel)
- 1 6" Calipers
- 1 0-1" Micrometer
- 1 6" Steel Ruler
- 1 8" or 10" Mill Bastard Cut File
- 1 Inch and Metric Hex Key Set

Optional preferred: (will make your life much easier)

- 1 60 Degree threading tool
- 1 T10293 Grizzly 7 Piece Indexable Carbide Set 3/8"